

Die File COPY

52/346



NP-33-77-73

October 12, 1977

Docket No. 50-346
License No. NPF-3

Mr. James G. Keppler
Regional Director, Region III
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137



Dear Mr. Keppler:

Reportable Occurrence NP-33-77-73
Davis-Besse Nuclear Power Station Unit 1
Date of Occurrence: September 17, 1977

Enclosed find three copies of Licensee Event Report NP-33-77-73 with a supplemental information sheet, which is being submitted in accordance with Technical Specification 6.9 to provide 30 day written notification of the subject occurrence.

Yours truly,

J Evans

Jack Evans
Station Superintendent
Davis-Besse Nuclear Power Station

JGE/JRL/ljk

Enclosures

cc: Dr. Ernst Volgenau, Director
Office of Inspection and Enforcement
Encl: 30 copies Licensee Event Report
30 copies Supplemental Information Sheet

Mr. William G. McDonald, Director
Office of Management
Information and Program Control
Encl: 3 copies Licensee Event Report
3 copies Supplemental Information Sheet

~~773030082~~

800 1150 677

THE TOLEDO EDISON COMPANY EDISON PLAZA 300 MADISON AVENUE TOLEDO, OHIO 43652

OCT 17 1977

S