

UNITED STATES

ATOMIC ENERGY COMMISSION DIRECTORATE OF REGULATORY OPERATIONS REGION III 799 ROOSEVELT ROAD

GLEN ELLYN, ILLINOIS 60137

TELEPHONE (312) 858-2660

March 14, 1973

Toledo Edison Company ATTN: Mr. Glenn J. Sampson Vice President, Power Edison Plaza 300 Madison Toledo, Ohio 43652

Docket No. 50-346

Gentlemen:

Thank you for your letter dated March 2, 1973, informing us of the steps you have taken to correct the items of noncompliance which we brought to your attention in our letter dated January 10, 1973. We will examine these matters during our next inspection.

A copy of RO Inspection Report No. 050-346/72-06 referenced in our letter of January 10 is enclosed. In accordance with Section 2.790 of the AEC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter, our letter of January 10, your letter of March 2, and the enclosed inspection report will be placed in the AEC's Public Document Room. If the inspection report contains information which you or your contractors believe to be proprietary, it is necessary that you submit a written application to this office, within 20 days of the date of this letter, requesting that such information be withheld from public disclosure. If such an application is submitted, it must identify the basis for which information is claimed to be proprietary. The application should be prepared so that proprietary information identified is contained in a separate part of the application, since the application will also be placed in the Public Document Room. If we do not receive an application to withhold information, or are not otherwise contacted within the specified time period, the enclosed report and the previously identified letters will be placed in the Public Document Room.

March 14, 1973

Id information, no reply to have questions concerning ad to discuss them with you.

- 2 -

Toledo Edison Company

Unless you wish to make application to withhold information, no reply to this letter is necessary; however, should you have questions concerning the enclosed inspection report, we will be glad to discuss them with you.

Sincerely yours,

Boyce H. Grier Regional Director

Enclosure: RO Inspection Rpt No. 050-346/72-06

bcc w/ltr dtd 3-2-73:
RO Chief, CB
RO:HQ (4)
Licensing (4)
DR Central Files
Regions I & II
PDR
Local PDR
NSIC
DTIE