

Appendix A

NOTICE OF VIOLATION

Toledo Edison Company

Docket No. 50-346

Based on the inspection conducted on July 17-21, 1978, it appears that certain of your activities were in noncompliance with NRC requirements, as noted below. The item is an infraction.

Contrary to 10 CFR 50.59(b), reactor operation with monitor RE 1003 (condenser vacuum pump discharge) inoperable since midyear 1977 was not evaluated to determine whether the change from the FSAR described operation involved an unreviewed safety question.

8001270 235