UNITED STATES NUCLEAR REGULATORY COMMISSION REGION III 799 ROOSEVELT ROAD GLEN ELLYN, ILLINDIS 50107

AUG 2 5 1976

Docket No. 50-346

8001300665

Tolado Siison Company ATTN: Mr. Lowell Roe Vice President Facilities Development Edison Plaza 300 Madison Avenue Toledo, Ohio 43652

Gentlemen:

This refers to the inspection conducted by Messrs. R. C. Knop and R. D. Martin of this office on August 16-17, 1976, of activities at Davis-Besse Unit 1 Construction Site authorized by NRC Construction Permit No. CPPR-80 and to the discussion of our findings with you at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No items of noncompliance with NRC requirements were identified during the course of this inspection.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this latter and the enclosed inspection report will be placed in the NRC's Public Document Room, except as follows. If this report contains information that you or your contractors believe to be proprietary, you must apply in writing to this office, within twenty days of your receipt of this letter, to withhold such information from public disclosure. The application must include a full statement of the reasons for which the information is considered proprietary, and should be prepared so that proprietary information identified in the application is contained in an enclosure to the application.

AUG 2 5 1976

Toledo Edison Company

- 2 -

We will gladly discuss any questions you have concerning this inspection.

Sincerely yours,

Gaston Fiorelli. Chief Reactor Operations and Nuclear Support Branch

Enclosure: IE Inspection Report No. 050-346/76-17

bcc w/encl: Central Files Reproduction Unit NRC 20b PDR Local PDR NSIC TIC

