IE FILE COPY



February 17, 1978

L78-095

Docket No. 50-346 License No. NPF-3 FILE: RR 2 (NP-33-78-18)

Mr. James G. Keppler Regional Director, Region III Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, Illinois 60137



Dear Mr. Keppler:

Reportable Occurrence 78-014 Davis-Besse Nuclear Power Station Unit 1 Date of Occurrence: January 23, 1978

Enclosed find three copies of Licensee Event Report 78-014 with a supplemental information sheet, which is being submitted in accordance with Technical Specification 6.9 to provide 30 day written notification of the subject occurrence.

Yours truly,

Terry D. Murray

Station Superintendent

Davis-Besse Nuclear Power Station

TDM/JRL/lik

Enclosures

cc: Dr. Ernst Volgenau, Director

Office of Inspection and Enforcement

Encl: 30 copies Licensee Event Report

30 copies Supplemental Information Sheet

Mr. William G. McDonald, Director

Office of Management

Information and Program Control

Encl: 3 copies Licensee Event Report

3 copies Supplemental Information Sheet

8001300668