

UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

1B FILE COPY

OCT 19 1976

Toledo Edison Company
ATTN: Mr. Lowell Roe
Vice President
Facilities Development
Edison Plaza
300 Madison Avenue
Toledo, Ohio 43652

Docket No. 50-346

Gentlemen:

This refers to this inspection conducted by Messrs. R. Martin, J. Kohler, and E. W. K. Lee on September 6-11 and 16-24, 1976, of activities at Davis Besse Unit 1 Construction site authorized by USNRC Construction Permit No. CPPR-80 and to the discussion of our findings with you and others of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in noncompliance with NRC requirements, as described under Enforcement Items in the Summary of Findings section of the enclosed inspection report. The inspection showed that action had been taken to correct the identified noncompliance and to prevent recurrence. Consequently, no reply to this noncompliance is required and we have no further questions regarding this matter at this time.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room, except as follows. If this report contains information that you or your contractors believe to be proprietary, you must apply in writing to this office, within twenty days of your receipt of this letter, to withhold such information from public disclosure. The application must include a full statement of the reasons for



8001300685

Toledo Edison Company

- 2 -

OCT 19 1976

which the information is considered proprietary, and should be prepared so that proprietary information identified in the application is contained in an enclosure to the application.

We will gladly discuss any questions you have concerning this inspection.

Sincerely yours,

Gaston Fiorelli, Chief
Reactor Operations and
Nuclear Support Branch

Enclosure:
IE Inspection Report
No. 050-346/76-19

bcc w/encl:
Central Files
Reproduction Unit NRC 20b
PDR
Local PDR
NSIC
TIC
U. Young Park, Power
Siting Commission