

UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

JUL 23 1976

Toledo Edison Company
ATTN: Mr. Lowell E. Roe
Vice President
Facilities Development
Edison Plaza
300 Madison Avenue
Toledo, Ohio 43652

Docket No. 50-346

FILE COPY

Gentlemen:

This refers to the inspection conducted by Messrs. C. Williams, F. Jablonski, T. Harpster, K. Naidu and R. Paolino of this office on June 8-11, 1976, of activities at Davis-Besse Nuclear Power Station, Unit 1, authorized by NRC Construction Permit No. CPPR-80 and to the discussion of our findings with you and others of your staff.

A copy of our report of this inspection is enclosed. The principle area examined during this inspection was the results to date of your reinspection of electrical installations as discussed in our letter dated May 30, 1975. Within this area and the other areas examined the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in noncompliance with NRC requirements, as described under Enforcement Items in the Summary of Findings section of the enclosed inspection report.

This notice is sent to you pursuant to the provisions of Section 2.201 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Section 2.201 requires you to submit to this office within thirty days of your receipt of this notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved.

With regard to Deficiency 1, we note that it represents a recurrence of a deficiency identified in IE Inspection Report No. 050-346/76-02. In your response to this item you should emphasize corrective actions which will prevent further recurrence.



8001300704

JUL 23 1976

Certain other activities, set forth under Other Significant Items in the Summary of Findings section of the enclosed inspection report, appear to be a deviation from commitments which you have made in previous correspondence with the Commission. Please advise us in writing within thirty days of the corrective action you have taken or plan to take, showing the estimated date of completion with regard to this deviation.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this notice, the enclosed inspection report, and your response to this notice will be placed in the NRC's Public Document Room, except as follows. If this report contains information that you or your contractors believe to be proprietary, you must apply in writing to this office, within twenty days of your receipt of this notice, to withhold such information from public disclosure. The application must include a full statement of the reasons for which the information is considered proprietary, and should be prepared so that proprietary information identified in the application is contained in an enclosure to the application.

We will gladly discuss any questions you have concerning this inspection.

Sincerely yours,

E. L. Jordan, Acting Chief
Reactor Construction and
Engineering Support Branch

Enclosure:
IE Inspection Report
No. 050-346/76-13

bcc w/encl:
Central Files
PDR
Local PDR
NSIC
TIC
U. Young Park, Power
Siting Commission
IE Mail and File Unit