



UNITED STATES  
ATOMIC ENERGY COMMISSION  
DIRECTORATE OF REGULATORY OPERATIONS  
REGION III  
799 ROOSEVELT ROAD  
GLEN ELLYN, ILLINOIS 60137

TELEPHONE  
(312) 858-2660

December 6, 1972

Toledo Edison Company  
ATTN: Mr. Glenn J. Sampson  
Vice President, Power  
420 Madison Avenue  
Toledo, Ohio 43601

Docket No. 50-346

Gentlemen:

The attached Directorate of Regulatory Operations Bulletin No. 72-3, "Limitorque Valve Operator Failures," is sent to you to provide you with information we received from the Northern States Power Company and the Commonwealth Edison Company concerning valve operator malfunctions experienced at their respective facilities. This information may relate to the performance of similar motor operated valves at your facilities. The Bulletin also requests certain action on your part related to this matter.

Should you have any questions concerning this matter, we will be pleased to discuss them with you.

Sincerely yours,

Boyce H. Grier  
Regional Director

Attachment:  
RO Bulletin No. 72-3

bcc: RO Files  
DR Central File  
PDR  
Local PDR

*50-346  
inquiry*

8001300 707