

UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION III  
799 ROOSEVELT ROAD  
GLEN ELLYN, ILLINOIS 60137

DEC 15 1976

Toledo Edison Company  
ATTN: Mr. Lowell E. Roe  
Vice President  
Facilities Development  
Edison Plaza  
300 Madison Avenue  
Toledo, Ohio 43652

Docket No. 50-346

Gentlemen:

Thank you for your letter of November 24, 1976, in response to our letter of October 20, 1976, relative to Inspection Report No. 050-346/76-18. We have reviewed your letter and find that additional information is required relative to two of the items, as discussed below. Our review of the remaining item indicates it has been satisfactorily addressed and your corrective action will be examined during a subsequent inspection.

In regard to the enforcement item relating to Criterion XIV, Appendix B, 10 CFR Part 50, your response does not address the problem as described in the Summary of Findings section of the report but only the example contained in the Report Details. Our concern is the failure to identify and control the inspection status of structures, systems, and components during and after installation, so that inadvertent damage or injury is precluded. Our inspection findings indicated that your electrical and instrumentation contractors do not have procedures implementing the requirements of Criterion XIV. Our review of Bechtel Power Corporation procedure No. BCM-FAP-100, Revision 3, finds this procedure to be consistent with Criterion XIV, however, the above described contractors do not appear to have knowledge of this procedure and are not following the procedural requirements.

Please advise us, in writing, of the corrective action you have taken, or plan to take, regarding this matter and the estimated date of completion of this corrective action.



8001300724

Toledo Edison Company


- 2 -

DEC 15 1976

Concerning the deviation item, we acknowledge your position as stated in your letter and during the discussions in our meeting of December 2, 1976. Our position remains as described in the inspection report. We are referring this matter to our headquarters for review, and you will be informed of the results of this review.

We will gladly discuss any questions you have concerning this matter.

Sincerely yours,



R. F. Heishman, Chief  
Reactor Construction and  
Engineering Support Branch

cc: Mr. J. Evans  
Davis-Besse, Station  
Superintendent

cc w/ltr dtd 11/24/76:  
Central Files  
Reproduction Unit NRC 20b  
PDR  
Local PDR  
NSIC  
TIC  
U. Young Park, Power  
Siting Commission