

AUG 10 1970

J. P. O'Reilly, Chief  
Reactor Inspection and  
Enforcement Branch  
Division of Compliance

TOLEDO EDISON COMPANY (DAVIS-BESSE) - DOCKET NO. 50-346

The enclosed report of the management meeting conducted subsequent to the initial quality assurance inspection is transmitted for information. Compliance found the applicant responsive to the comments made. We continue, however, to have concern about the timeliness of program development and the adequacy of manning.

We will pay particular attention to these matters in our continuing inspection program.

J. B. Henderson  
Senior Construction Engineer  
Division of Compliance

Enclosure:  
CO Rpt No. 346/70-3

cc w/enclosure:  
E. G. Case, DRS (3)  
P. A. Morris, DRL  
R. S. Boyd, DRL (2)  
R. C. DeYoung, DRL (2)  
D. J. Skovholt, DRL (3)  
P. W. Howe, DRL (2)  
L. Kornblith, Jr., CO  
R. W. Kirkman, CO:I  
J. G. Davis, CO:II  
B. H. Grier, CO:III  
D. I. Walker, CO:IV  
R. W. Smith, CO:V  
W. E. Vetter, CO:III  
REG Central File

IP	OFFICE ► CO	CO	CO	
SURNAME ► JBHenderson:kbj	F& Nolan	JPOT	Reilly	
DATE ► 8/10/70	8/10/70	8/10/70		8001310546