



UNITED STATES
ATOMIC ENERGY COMMISSION
DIVISION OF COMPLIANCE
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

TELEPHONE
(312) 858-2660

March 9, 1972

Toledo Edison Company
ATTN: Mr. Glenn J. Sampson
Vice President, Power
420 Madison Avenue
Toledo, Ohio 43601

Docket No. 50-346

Gentlemen:

This refers to the inspection conducted by Mr. Oiler of this office on February 23 - 24, 1972, at the Dresser Industries plant, located in Alexandria, Louisiana, of activities related to construction of the Davis-Besse facility authorized by AEC Construction Permit No. CFFR-80 and to the discussion of our findings at the conclusion of the inspection with Messrs. Richardson and Brown of the Dresser Industries staff.

The area examined during the inspection was the manufacture of main steam safety valves. Within this area, the inspection consisted of selective examination of procedures and representative records, interviews with plant personnel, and observations by the inspector.

No items of noncompliance with AEC requirements were identified within the areas examined during this inspection.

No reply to this letter is necessary; however, should you have questions concerning this inspection we will be glad to discuss them with you.

Sincerely yours,

Boyce H. Grier
Regional Director

cc: L. E. Roe, Project Engineer
N. L. Wadsworth, General
Superintendent
J. A. Lenardson, Quality
Assurance Engineer

bcc: J. B. Henderson, CO
L. Kornblith, CO
R. H. Engelken, CO
P. A. Morris, DRL
CO Files
DR Central Files
PDR
Local FDR
NSIC
R. L. Shannon, DTIE

8001310582