

UNITED STATES
ATOMIC ENERGY COMMISSION
DIVISION OF COMPLIANCE
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

TELEPHONE
(312) 8-2600

March 13, 1972

Colorado Edison Company
Attn: Mr. Glenn J. Sampson
Vice President, Power
420 Madison Avenue
Toledo, Ohio 43601

Docket No. 50-346

Gentlemen:

Thank you for your letter dated March 6, 1972, and the attached report, covering your investigation of the circumstances associated with apparent concrete cylinder low strength indications, submitted in response to our letter dated February 20, 1972. We will examine this matter further during subsequent inspections.

Your cooperation with us is appreciated.

Sincerely yours,

Boyce H. Grier
Regional Director

cc: L. E. Roe, Project Engineer
H. L. Wadsworth, General
Superintendent
J. A. Leonardson, Quality
Assurance Engineer

bcc w/lcr dtd 3-6-72:

J. B. Henderson, CO
L. Kornblith, CO
R. H. Engelken, CO
P. A. Morris, DRL
CO Files

DR Central Files

PDR

Local PDR

NSIC

R. L. Shannon, DTIE

8001310589

Q