


71P. 3  
77-89  
D. Lantieri

IE FILE COPY,



L77-428

FILE: RR.2 (NP-33-77-89)

December 1, 1977

Docket No. 50-346  
License No. NPF-3



Mr. James G. Keppler  
Regional Director, Region III  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

Reportable Occurrence NP-33-77-89  
Davis-Besse Nuclear Power Station Unit 1  
Date of Occurrence: November 7, 1977

Enclosed find three copies of Licensee Event Report NP-33-77-89 with a supplemental information sheet, which is being submitted in accordance with Technical Specification 6.9 to provide 30 day written notification of the subject occurrence.

Yours truly,

*Terry D. Murray*

Terry D. Murray  
Station Superintendent  
Davis-Besse Nuclear Power Station

TDM/JRL/ljk

Enclosures

cc: Dr. Ernst Volgenau, Director  
Office of Inspection and Enforcement  
Encl: 30 copies Licensee Event Report  
30 copies Supplemental Information Sheet

Mr. William G. McDonald, Director  
Office of Management  
Information and Program Control  
Encl: 3 copies Licensee Event Report  
3 copies Supplemental Information Sheet

DEC 3 1977

8002040657

