

D. Lankam




January 11, 1978

L78-011

FILE: RR 2 (NP-33-77-113)

Docket No. 50-346  
License No. NPF-3



Mr. James G. Keppler  
Regional Director, Region III  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

Reportable Occurrence NP-33-77-113  
Davis-Besse Nuclear Power Station Unit 1  
Date of Occurrence: December 16, 1977

Enclosed find three copies of Licensee Event Report NP-33-77-113 with a supplemental information sheet, which is being submitted in accordance with Technical Specification 6.9 to provide 30 day written notification of the subject occurrence.

Yours truly,

Terry D. Murray  
Station Superintendent  
Davis-Besse Nuclear Power Station

TDM/JRL/ljk

Enclosures

cc: Dr. Ernst Volgenau, Director  
Office of Inspection and Enforcement  
Encl: 30 copies Licensee Event Report  
30 copies Supplemental Information Sheet

Mr. William G. McDonald, Director  
Office of Management  
Information and Program Control  
Encl: 3 copies Licensee Event Report  
3 copies Supplemental Information Sheet

~~720920083~~

JAN 16 1978

A002/5 \*