O. Lankon

IE FILE COPY



November 17, 1977

L77-384

Docket No. 50-346 License No. NPF-3 FILE: RR.2 (NP-32-77-18)

----

Mr. James G. Keppler Regional Director, Region III Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission

799 Roosevelt Road Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

Reportable Occurrence NP-32-77-18 Davis-Besse Nuclear Power Station Unit 1 Date of Occurrence: November 8, 1977

Enclosed find three copies of Licensee Event Report NP-32-77-18 with a supplemental information sheet, which is being submitted in accordance with Technical Specification 6.9 to provide 14 day written notification of the subject occurrence.

Yours truly,

- my Darwin

Terry D. Murray Station Superintendent Davis-Besse Nuclear Power Station

TDM/JRL/1jk

Enclosures

cc: Dr. Ernst Volgenau, Director Office of Inspection and Enforcement Encl: 40 copies Licensee Event Report

40 copies Supplemental Information Sheet

Mr. William G. McDonald, Director Office of Management Information and Program Control Encl: 3 copies Licensee Event Report 3 copies Supplemental Information Sheet

2 copies Telecopied Report