Contral file



Stephen H. Howell Vice President

General Offices: 1945 West Parnall Road, Jackson, Michigan 49201 \* Area Code 517 788-0453

July 27, 1978 Howe-133-78

Mr J G Keppler, Regional Director Nuclear Regulatory Commission Region III 799 Roosevelt Road Glen Ellyn, IL 60137

MIDLAND PROJECT DOCKET NO 50-329, 50-330 IE BULLETIN 78-06 FILE: 0505.2 SERIAL: 5652

Your IE Bulletin 78-06 on "Defective Cutler-Hammer Type M Relays with DC Coils" requested that investigation be made to determine whether Cutler-Hammer type M relays with dc coils were used or planned for use in the safety systems at the Midland Plant Units 1 and 2.

Through our investigation, we have determined that there are no Cutler-Hamar type M relays with dc coils which fall into this category.

igh 20 Dowell

SHH/jg

CC: Director, NRC Office of Inspection & Enforcement Director of Nuclear Reactor Regulation

JUL 0 1 1978

AO Z

8006160 406