

UNITED STATES

ATOMIC ENERGY COMMISSION DIRECTORATE OF REGULATORY OPERATIONS REGION III 799 ROOSEVELT ROAD

GLEN ELLYN, ILLINOIS 60137

TELEPHONE (312) 858-2660

FEB 2 0 1974

Consumers Power Company ATTN: Mr. Stephen H. Howell Vice President 1945 W. Parnall Road Jackson, Michigan 49201

Docket No. 50-329 Docket No. 50-330

Gentlemen:

This refers to the inspection conducted by Mr. C. Williams of this office on January 29, 1974, of activities at the Midland site authorized by Licenses No. CPPR-81 and No. CPPR-82 and to the discussion of our findings with Mr. Siager and others of your staff at the conclusion of the inspection.

A copy of our report of this inspection is enclosed and identifies the areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, interviews with plant personnel, and observations by the inspector.

No violations of AEC requirements were identified within the scope of this inspection.

In accordance with Section 2.790 of the AEC's "Rules of Practice," Part 2, Title 10. Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the AFC's Public Document Room. If this report contains any information that you or your contractors believe to be proprietary, it is necessary that you make a written application to this office, within twenty days of your receipt of this letter, to withhold such information from public disclosure. Any such application must include a full statement of the reasons for which it is claimed that the information is proprietary, and should be prepared so the proprietary information identified in the application is contained in a separate part of the document. Unless we receive an application to withhold information or are otherwise contacted within the specified time period, the written material identified in this paragraph will be placed in the Public Document Room.

> THIS DOCUMENT CONTAINS POOR QUALITY PAGES

8006200698

Should you have any questions concerning this inspection, we will be glad to discuss them with you.

Sincerely yours,

James G. Keppler Regional Director

Enclosure:

RO Inspection Rpts No. 050-329/4-02 and No. 050-330/74-02

bcc: RO Chief, FS&EB

RO:HQ (4) Licensing (4) DR Central Files

RO Files

Local PDR

NSIC

OGC, Beth, P-506A

Ronald Callen

J. Murray, GC (2) Dr. Wayne E. North

Myron M. Cherry