U. S. ATOMIC ENERGY COMMISSION DIRECTORATE OF REGULATORY OPERATIONS

REGION III

Report of Construction Inspection

RO Inspection Report No. 050-329/74-06 RO Inspection Report No. 050-330/74-06

Licensee: Consumers Power Company

1945 West Parnall Road Jackson, Michigan 49201

Midland Plant, Units 1 and 2

Midland, Michigan

License No. CPPR-81 License No. CPPR-82

Category: A

Type of Facility: PWR (B&W) - Unit 1, 650 Mwe

Unit 2, 818 Mwe

Type of Inspection: Special, Unannounced

Date of Inspection: March 15, 1974

Dates of Previous Inspection: March 6&7, 1974 (Construction)

Principal Inspector: R. A. Rohrbacher

Accompanying Inspector: None

Reviewed By: W. E. Vetter, Chief W. & With Reactor Construction

SUMMARY OF FINDINGS

Enforcement Action

A. Violations

No violations of AEC requirements were identified during the inspection.

B. Safety Matters

No safety matters were identified during the inspection.

Licensee Action on Previously Identified Enforcement Matters

Not applicable to this special inspection.

Design Changes Not applicable.

Unusual Occurrences None identified.

Other Significant Findings

A. Current Findings

An inspection at the corporate offices of the Consumers Power Company (CP) was conducted to review corporate management files. The intent was to determine whether the subject records indicated situations wherein the licensee may have withheld information which should have been reported to the AEC. No evidence was found which indicated, or suggested, that reportable matter had not been previously reported to the AEC as required.

B. Unresolved Matters

No new unresolved matters were identified during the current inspection.

C. Status of Previously Reported Unresolved Matters

No previously reported unresolved matters were involved with this special inspection.

Management Interview

A. The following persons attended the management interview at the conclusion of the inspection:

Consumers Power Company (CP)

- S. H. Howell, Vice President
- W. E. Kessler, Project Manager
- G. S. Keeley, Director of Quality Assurance Services
- H. W. Slager, Project Quality Assurance Supervisor
- B. Matters discussed and comments, on the part of management personnel, were as follows:

The inspectors stated that the following CP corporate office files, relative to the Midland Plant, were reviewed: (1) general information, (2) correspondence, (3) Project Quality Assurance Services - Midland Project, and (4) monthly reports. The inspectors further stated that no problems were identified during this review, and the results of the review raised no substantial questions. Licensee personnel acknowledged this information.

REPORT DETAILS

Persons Contacted

Only the individuals listed under the Management Interview Section of this report were contacted during the inspection.

Results of Inspection

The following CP corporate files, relative to the Midland Plant, were reviewed during the current inspection. No problems were identified during this review.

- Correspondence and General Files (Chronological) G. S. Keeley
 Correspondence and other information in the subject file (about 90 items) were reviewed for the period from October 1, 1973, through March 13, 1974.
- Reports dated from October 1973 through March 1974 were reviewed.
 - Correspondence and General Files (Chronological) H. W. Slager
 Information in this file, from October 1973 to date, was reviewed.
 - 4. Correpondence and General Files (Chronological) W. E. Kessler Information in this file for 1973 and 1974, to date, was reviewed.
 - 5. Midland Project Monthly Reports W. E. Kessler (to S. H. Howell)

 Information in this file from 1970 to date was reviewed.
 - 6. Project Quality Assurance Services Midland Project File 10.3
 (Project or Engineering Services Witness Hold Points)

 This file was reviewed in its entirety.
 - 7. Project Quality Assurance Services Midland Project Files 16.6, 16.7, 16.8, and 16.12 (NCR's on Contractor's, Bechtel Audits)
 Information in these files were reviewed. Most of the material in these files were dated from October 1973 to March 1974.



UNITED STATES

ATOMIC ENERGY CO VIMISSION DIRECTORATE OF REGULATORY OPERATIONS REGION III 799 ROOSEVELT ROAD

GLEN ELLYN, ILLINOIS 60137

TELEPHONE (312) 858-2660

Α.	RO Inspection Report No. 050-329/74-06 and 050-330/74-06		
	Transmittal Date : Apr	ril 15, 1974	
	Distribution:	Distribution:	
	RO Chief, FS&EB	RO Chief, FS&EB	
	RO: HQ (5)	RO:HQ (4)	
	DR Central Files	L:D/D for Fuels & Materials	
	Regulatory Standards (3)	DR Central Files	
	Licensing (13) RO Files	RO Files	
в.	RO Inquiry Report No.		
	Distribution:	Distribution:	
	RO Chief, FS&EB	RO Chief, FS&EB	
	RO:HQ (5)	RO:HQ	
	DR Central Files	DR Central Files	
	Regulatory Standards (3) Licensing (13) RO Files	RO Files	
c.	Incident Notification From:		
		(Licensee & Docket No. (or License No.)	
	Transmittal Date :		
	Distribution:	Distribution:	
	RO Chief, FS&EB	RO Chief, FS&EB	
	RO:HQ (4)	RO:HQ (4)	
	Licensing (4)	L:D/D for Fuels & Materials	
	DR Central Files	DR Central Files	
	RO Files	RU Files	