UNITED STATES

NUCLEAR REGULATORY COMMISSION

REGION III

799 ROOSEVELT ROAD

GLEN ELLYN, ILLINOIS 60137

Controlpho

AUG 8 1975

Consumers Power Company
ATTN: Mr. Stephen H. Howell
Vice President
1945 West Parnall Road
Jackson, Michigan 49201

Docket No. 50-329 Docket No. 50-330

Gentlemen:

This refers to the inspection conducted by Mr. Yin of this office on July 16-17, 1975, of activities at Midland Units 1 and 2 authorized by NRC Construction Permits No. CPPR-81 and No. CPPR-82 and to the discussion of our findings with you and messrs. Keeley and Slager of your staff at the conclusion of the inspection.

A copy of our report of this inspection is enclosed and identifies the area examined during the inspection. Within this area, the inspection consisted of a selective examination of procedures and representative records, interviews with plant personnel, and observations by the inspector.

No items of noncompliance with NRC requirements were identified within the scope of this inspection.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room. If this report contains any information that you or your contractors believe to be proprietary, it is necessary that you make a written application to this office, within twenty days of your receipt of this letter, to withhold such information from public disclosure. Any such application must include a full statement of the reasons for which it is claimed that the information is proprietary, and should be prepared so the proprietary information identified in the application is contained in a separate part of the document. Unless we receive an application to withhold information or are otherwise contacted within the specified time period, the written material identified in this paragraph will be placed in the Public Document Room.



8007100 6 38

Q 牙引光

No reply to this letter is necessary; however, should you have any questions concerning this inspection, we will be glad to discuss them with you.

Sincerely yours,

D. M. Hunnicutt, Chief Construction and Engineering Support Branch

Enclosure: IE Inspection Reports No. 050-329/75-05 and No. 050-330/75-05

bcc w/encl: PDR Local PDR NSIC TIC OGC, Beth, P-506A Ronald Callen Dr. W. E. North Myron M. Cherry