

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | 0 | R | T | N | P | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5
7 8 9 14 15 25 26 30 37 38 39

CON'T
01 | L | 6 | 0 | 5 | 0 | - | 0 | 3 | 4 | 4 | 7 | 0 | 7 | 0 | 1 | 8 | 0 | 8 | 0 | 7 | 1 | 6 | 8 | 0 | 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
02 | NO. 80-12: DURING AN ENGINEERING WALKDOWN OF PIPING, THREE SEISMIC
03 | RESTRAINTS WERE FOUND TO BE MISSING FROM A STEAM DRAIN LINE ON THE STEAM
04 | TURBINE-DRIVEN AUXILIARY FEEDWATER PUMP. THE DIESEL-DRIVEN AUXILIARY
05 | FEEDWATER PUMP WAS UNAFFECTED.
06 |
07 |
08 |

09 | C | H | 11 | A | 12 | E | 13 | S | U | P | O | R | T | 14 | B | 15 | Z | 16
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
17 | LER/RO REPORT NUMBER | 18 | S | 19 | 0 | 20 | 1 | 21 | 2 | 22 | 0 | 23 | 3 | 24 | L | 25 | 1 | 26 | 0 | 27 | 1 | 28 | 0 | 29 | 1 | 30 | 0 | 31 | 1 | 32 | 0 | 33 | 34 | 35 | 36 | 37 | 38 | 39 | 40 | 41 | 42 | 43 | 44 | 45 | 46 | 47 | 48 | 49 | 50
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NRPD-4 FORM SUB. PRIME COMP SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
10 | THE RESTRAINTS WERE NEVER INSTALLED DURING CONSTRUCTION. CORRECTIVE
11 | ACTION WAS TO INSTALL THE RESTRAINTS.
12 |
13 |
14 |

15 | D | 28 | 0 | 0 | 0 | 29 | NA | 30 | A | 31 | ENGINEER OBSERVATION | 32
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
16 | Z | 33 | Z | 34 | NA | 35 | NA | 36
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
17 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
18 | 0 | 0 | 0 | 40 | NA | 41
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
19 | Z | 42 | NA | 43
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
20 | N | 44 | NA | 45
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

NAME OF PREPARER John C. Perry PHONE: 503/556-3713, ext. 228

8007280 553