


TUBECO INC.



123 VARICK AVENUE
BROOKLYN, N.Y. 11237
PIPE FABRICATING
TEL. - (212) 386-0700
ITT TELEX NO. 425529
WU TELEX NO. 12-9203

July 7, 1980

U.S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

Att: Mr. Karl V. Seyfrit, Director

Subject: Docket No. 9990021f, Letter dated June 17, 1980

Gentlemen:

In response to your letter dated June 17, 1980 with reference to the Notice of Deviation, item H, we are enclosing a revised page 8 (of 14) adding the commitment H.2, which is intended to provide an independent follow-up on corrective and preventive actions.

Very truly yours,

TUBECO, INC.

L. Katz
Director of Quality Assurance

LK:jfl

Enclosure

cc: Wm. Goldsmith



8007290368

DETAILED RESPONSE TO NRC LETTER DATED APRIL 18, 1980 - DOCKET 99900216
REVISED JULY 7, 1980.

DEVIATION NOTICE H

1. A PROCEDURE ADDRESSING CONTROL OF FURNACE SETTINGS WAS NOT ESTABLISHED UNTIL MARCH 26, 1980, AND AS A RESULT OF IDENTIFICATION OF ITS ABSENCE BY THE INSPECTOR.

CORRECTIVE ACTION:

H.1 PROCEDURE H-306, AVAILABLE IN DRAFT FORM AT TIME OF INSPECTION, WAS COMPLETED AND DISTRIBUTED TO THE PERSONNEL INVOLVED.

ACTION COMPLETED.

ACTION TO PREVENT RECURRENCE:

R1

H.2 LOG OF CORRECTIVE ACTION COMMITMENTS WILL BE FURNISHED TO THE VICE-PRESIDENT FOR ADMINISTRATION FOR FOLLOW UP.

ACTION COMPLETED.