

UNITED STATES NUCLEAR REGULATORY COMMISSION REGION IV 611 RYAN PLAZA DRIVE, SUITE 1000 ARLINGTON, TEXAS 76012

VIA AIR MAIL

2 9 APR 1980

Docket No. 99900355/80-01

Hirata Valve Industry Co., Ltd. Kawasaki Division Attn: Mr. Y. Hirata Vice President, Kawasaki Division 15, Hisamoto, Takatsu-Ku Kawasaki-City, Kanagawa-Pref., JAPAN

Gentlemen:

Thank you for your letter of April 15, 1980, in response to our letter dated February 22, 1980. As a result of our review, we find that additional information is needed on the following Items in the Notice of Deviation:

- Item C Please describe what actions have been taken that will provide assurance of the effectivity of personnel training and indoctrination, with respect to continued compliance with calibration program requirements.
- Item D Your response fails to provide any corrective action measures relative to the improper signoff by Hirata Valve personnel of the identified cleaning operation.

Please provide this additional information within twenty (20) days in order that we may complete our review in a timely manner.

Sincerely,

Uldis Potapcvs, IPT

Vendor Inspection Branch