

Appendix A

NOTICE OF VIOLATION

Union Electric Company

Docket No. 50-483

Based on the results of the NRC inspection conducted on May 1-30, 1980, it appears that certain of your activities were not conducted in full compliance with NRC requirements as noted below. This item is a deficiency.

10 CFR 50, Appendix B, Criterion 5 and SNUPPS PSAR paragraph 17.1.5 requires that activities affecting quality . . . shall be accomplished in accordance with these instructions, procedures, or drawings.

SNUPPS PSAR paragraph 3.12 states, that the QA requirements for . . . storage . . . are in accordance with ANSI N45.2.2. Daniel International Procedure AP-IV-09, "Storage and Maintenance" paragraph 3.6 states that, "Maintenance shall as a minimum, meet the requirements of reference 2.5. (Reference 2.5 is ANSI N45.2.2)."

Contrary to the above, covers and/or panel closures are not being routinely reinstalled at the completion of work on electrical panels.

8607300-64