July 18, 1980

In reply, please refer to LAC-7034

DOCKET NO. 50-409

Mr. James G. Keppler Regional Director U. S. Nuclear Regulatory Commission Directorate of Regulatory Operations Region III 799 Roosevelt Road Glen Ellyn, Illinois 60137

SUBJECT: DAIRYLAND POWER COOPERATIVE

LA CROSSE BOILING WATER REACTOR (LACEWR) PROVISIONAL OPERATING LICENSE NO. DPR-45

IE BULLETIN 80-10 - CONTAMINATION OF NONRADIOACTIVE

SYSTEM AND RESULTING POTENTIAL FOR UNMONITORED,

UNCONTROLLED RELEASE OF RADIOACTIVITY TO ENVIRONMENT

Reference: (1) NRC Letter, Keppler to Linder,

dated May 6, 1980.

(2) DPC Letter, Linder to Keppler, (LAC-7024) dated July 11, 1980.

Dear Mr. Keppler:

This is to verify that the action specified in our letter (Reference 2) as required by the DPC response to Item 2 of the subject bulletin contained in your letter (Reference 1), was completed on July 14, 1978. Sampling of the heating boiler for contamination was added to the appropriate Health and Safety Procedure.

If you have any questions regarding this response, please contact us.

Very truly yours,

DAIRYLAND POWER COOPERATIVE

Frank Linder (4)

Frank Linder, General Manager

FL:GSB:af

BUL 2 1 1910