DEPARTMENT OF THE NAVY NAVAL FACILITIES ENGINEERING COMMAND 200 STOVALL'STREET ALEXANDRIA, VA 22332

(PDR 71-5071 (PDR 71-5071 (PDR 71-5830 (332) 71-5830 (332) 71-6786 JL 20 PH 3 06

3256B2

SER 93

2 JUL 198

511911

- - TG Mr. Richard Odegaarden Transportation Certification Branch Division of Fuel Cycle and Material Safety U. S. Nuclear Regulatory Commission Washington, DC 20555

Dear Mr. Odegaarden:

The Naval Facilities Engineering Command no longer has a need for Certificates of Compliance (COC) 5071, 5830 and 6786. The radicise tope thermoelectric generators (RTGs) covered by these Certificates have been transferred to other Navy commands as follows:

Command	RTG	COC	License No.
Naval Energy and Environmental Support Activity	URIPS-P1 SNAP-21	5071 5830	0+=-07316-03 04-07316-03
Naval Support Force Antarctica	URIPS-P1 SNAP-21 URIPS-8	5071 5830 6786	04-19167-01 04-19167-01 04-19167-01

As you discussed with Lieutenant Bob Evans of the Naval Support Force Antarctica (NSFA) on 3 June 1980, it is requested that Certificates 5071, 5830 and 6786 be renewed and reissued to NSFA and that the Naval Energy and Environmental Support Activity, formerly the Naval Nuclear Power Unit, be registered as a user of Certificates 5071 and 5830. The complete addresses of these commands are:

Officer in Charge Naval Energy and Environmental Support Activity Radiological Affairs Support Office Port Hueneme, CA 93043

Commander U. S. Naval Support Force Antarctica FPO San Francisco 96601

The Officer in Charge of the Naval Energy and Environmental Support Activity and the Commander of the Naval Support Force Antarctica concur in this request.

Jene Hending

G. W. HENDRIX By direction

16915

Copy to: NEESA (Code 20) CNSFA (Code A33)

8008070 217

DEPARTMENT OF THE NAVY NAVAL FACILITIES ENGINEERING COMMAND 200 STOVALL STREET ALEXANDRIA, VA 22332

- JJL 20 PM 3 05

Mr. Richard Odegaarden Transportation Certification Branch Division of Fuel Cycle and Material Safety U. S. Nuclear Regulatory Commission Washington, DC 20555

Dear Mr. Odegaarden:

The Naval Facilities Engineering Command no longer has a need for Certificates of Compliance (COC) 5071, 5830 and 6786. The radioisotope thermoelectric generators (RTGs) covered by these Certificates have been transferred to other Navy commands as follows:

Command	RTG	COC	License No.
Naval Energy and Environmental Support Activity	URIPS-P1 SNAP-21	5071 5830	04-07316- 0 3 04-07316- 0 3
Naval Support Force Antarctica	URIPS-P1 SNAP-21 URIPS-8	5071 5830 6786	04-19167-01 04-19167-01 04-19167-01

As you discussed with Lieutenant Bob Evans of the Naval Support Force Antarctica (NSFA) on 3 June 1980, it is requested that Certificates 5071, 5830 and 6786 be renewed and reissued to NSFA and that the Naval Energy and Environmental Support Activity, formerly the Naval Nuclear Power Unit, be registered as a user of Certificates 5071 and 5830. The complete addresses of these commands are:

Officer in Charge Naval Energy and Environmental Support Activity Radiological Affairs Support Office Port Hueneme, CA 93043

Commander U. S. Naval Support Force Antarctica FPO San Francisco 96601

16915

71-5071 1-5830 71-6786

3256B2

SER 93

2 JUL 198

The Officer in Charge of the Naval Energy and Environmental Support Activity and the Commander of the Naval Support Force Antarctica concur in this request.

Jene Henderig

G. W. HENDRIX By direction

Copy to: NEESA (Code 20) CNSFA (Code A33) DEPARTMENT OF THE NAVY NAVAL FACILITIES ENGINEERING COMMAND 200 STOVALL STREET ALEXANDRIA, VA 22332

eso

3256B2

SER 93

2 JUL 198

Mr. Richard Odegaarden

Transportation Certification Branch Division of Fuel Cycle and Material Safety U. S. Nuclear Regulatory Commission Washington, DC 20555

Dear Mr. Odegaarden:

The Naval Facilities Engineering Command no longer has a need for Certificates of Compliance (COC) 5071, 5830 and 6786. The radioisotope thermoelectric generators (RTGs) covered by these Certificates have been transferred to other Navy commands as follows:

Command	RTG	COC	License No.
Naval Energy and Environmental Support Activity	URIPS-P1 SNAP-21	5071 5830	04-07316-03 04-07316-03
Naval Support Force Antarctica	URIPS-P1 SNAP-21 URIPS-8	5071 5830 6786	04-19167-01 04-19167-01 04-19167-01

As you discussed with Lieutenant Bob Evans of the Naval Support Force Antarctica (NSFA) on 3 June 1980, it is requested that Certificates 5071, 5830 and 6786 be renewed and reissued to NSFA and that the Naval Energy and Environmental Support Activity, formerly the Naval Nuclear Power Unit, be registered as a user of Certificates 5071 and 5830. The complete addresses of these commands are:

Officer in Charge Naval Energy and Environmental Support Activity Radiological Affairs Support Office Port Hueneme, CA 93043 Commander U. S. Naval Support Force Antarctica FPO San Francisco 96601

The Officer in Charge of the Naval Energy and Environmental Support Activity and the Commander of the Naval Support Force Antarctica concur in this request.

Sene Hending

G. W. HENDRIX By direction

16915

71-5071

1911

Copy to: NEESA (Code 20) CNSFA (Code A33)