



**CONSUMERS
POWER
Company**

James W Cook
Vice President, Midland Project

General Offices: 1945 West Parnall Road, Jackson, Michigan 49201 • (517) 788-0640

August 1, 1980

Mr J G Keppler, Regional Director
Office of Inspection and Enforcement
US Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

MIDLAND PROJECT

UNIT NO 1, DOCKET NO 50-329

UNIT NO 2, DOCKET NO 50-330

UNIT NO 1, REACTOR VESSEL BROKEN ANCHOR BOLT

FILE: 0.4.9.35 UFI: 73*10*01, 02111(S) 21114(E) Serial: 8809

- References:
1. S H Howell letters to J G Keppler; Midland Nuclear Plant; Unit No 1, Docket No 50-329; Unit No 2, Docket No 50-330; Unit No 1 Reactor Vessel Broken Anchor Bolt;
 - a. Howe-311-79; dated December 14, 1979
 - b. Howe-267-79; dated October 12, 1979
 - c. How 51-80; dated March 3, 1980
 - d. Howe 50-80; dated April 30, 1980
 2. J W Cook letter to J G Keppler; Midland Nuclear Plant; Serial 8971; dated May 16, 1980
 3. J W Cook letter to J G Keppler; Midland Nuclear Plant; Serial 9330; dated July 24, 1980

References 1 and 2 were interim 50.55(e) reports concerning broken anchor bolts in the Unit 1 reactor vessel support skirt. It was reported in Reference 2 that we would send a further 50.55(e) report by August 1, 1980. This letter, in conjunction with Reference 3, fulfills that commitment. Reference 3 provides a report on the reactor pressure vessel support modification. The distribution of Reference 3 is identical to this letter.

Another 50.55(e) report, either interim or final, will be sent on or before October 31, 1980.

WRB/ch

James W. Cook

3019
5
1/0

8008080254

CC Director, Office of Inspection & Enforcement
Att Mr Victor Stello, USNRC (38)

Director, Office of Inspection & Enforcement
[REDACTED]