

JUN 11 1980

APPENDIX A

Department of the Navy
USS JASON (AR-8)
FPO San Francisco, California

License No. 04-17765-01

NOTICE OF VIOLATION

Based upon the results of the NRC inspection conducted on May 22, 1980 certain activities under your license appear to be in noncompliance with NRC requirements as identified below:

1. Contrary to 10 CFR 34.29(b), the entrance that is used for personnel access to the high radiation area in the permanent radiographic installation did not have an audible signal which will actuate when an attempt is made to enter the installation while the source is exposed.

This item is an infraction.

2. Contrary to 10 CFR 20.401(b), no record was maintained of the radiation surveys conducted at three feet from the packages received containing licensed materials, pursuant to 10 CFR 20.205(c). These packages were received on December 19, 1979 and March 18, 1980, each containing 30 curies of iridium-192.

This item is a deficiency.

3. Contrary to 10 CFR 20.407, the statistical summary report of the personnel monitoring information was not submitted to the NRC within the first quarter of calendar year 1980. The summary report was submitted on May 16, 1980.

This item is a deficiency.

8008110 653