



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

October 25, 1989

Docket No. 50-346

Toledo Edison Company
ATTN: Mr. Donald Shelton
Vice President
Nuclear
Edison Plaza
300 Madison Avenue
Toledo, OH 43652

Gentlemen:

Enclosed is a document which describes the Region III Oversight of Licensee Self-Initiated Configuration Management Programs. I believe that these licensee programs are very important, since both licensee and NRC inspections under these programs have identified significant safety findings. I am forwarding the enclosed document to you so that you will be aware of Region III's approach relative to this important subject.

If you have any questions or comments on this approach, I would be pleased to discuss them with you.

Sincerely,

A. Bert Davis
Regional Administrator

Enclosure: As stated

cc w/enclosure:

L. Storz, Plant Manager

DCD/OCE (RIDS)

Licensing Fee Management Branch

Resident Inspector, RIII

James W. Harris, State of Ohio

Roger Suppes, Ohio

Department of Health

A. Grandjean, State of Ohio,

Public Utilities Commission

E. G. Greenman, RIII

H. J. Miller, RIII

C. E. Norelius, RIII