TOLEDO

August 26, 1980

L80-1054

FILE: RR 2 (NP-32-80-14)

Docket No. 50-346 License No. NPF-3

Mr. James G. Keppler Regional Director, Region III Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

Reportable Occurrence 80-060 Davis-Besse Nuclear Power Station Unit 1 Date of Occurrence: August 13, 1980

Enclosed are three copies of Licensee Event Report 80-060 with a supplemental information sheet which is being submitted in accordance with Technical Specification 6.9 to provide 14 day written notification of the subject occurrence.

Yours truly,

Terry D. 201 may / Bols

Terry D. Murray Station Superintendent Davis-Besse Nuclear Power Station

TDM/1jk

Enclosure

cc: Mr. Victor Stello, Director Office of Inspection and Enforcement Encl: 40 copies LER 80-060 2 copies telecopy

> Mr. Norman Haller, Director Office of Management Program Analysis Encl: 3 copies LER 80-060

Mr. Luis Reyes NRC Resident Inspector Encl: 1 copy LER 80-060