

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | N | Y | J | A | F | I | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | - | 0 | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5
7 3 9 14 15 25 26 30 37 CAT 38

CON'T
0 1 | R | E | P | O | R | T | S | O | U | R | C | E | L | 5 | 0 | 5 | 0 | 0 | 0 | 3 | 3 | 3 | 7 | 0 | 8 | 0 | 5 | 8 | 0 | 3 | 0 | 8 | 2 | 8 | 8 | 0 | 9
7 3 30 31 38 39 44 45 50 51 56 57 62 63 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 | During normal shutdown, while conducting Instrument Surveillance Procedure E-ISP-8,
0 3 | Core Spray System pipe break detection switches 14-DPIS-43A and 43B were found set
0 4 | at 1.5 and 2.05 PSID respectively when required to be set at less than or equal to
0 5 | 0.5 PSID by TS Table 3.2-2. Instrument 14-DPIS-43B was also found set at 0.93 PSID
0 6 | on August 18, 1980.
0 7 |
0 8 |

0 9 | SYSTEM CODE: S F 11; CAUSE CODE: E 12; CAUSE SUBCODE: E 13; COMPONENT CODE: I N S T R U 14; COMP SUBCODE: S 15; VALVE SUBCODE: Z 16
17 | LER NO REPORT NUMBER: 8 0; SEQUENTIAL REPORT NO.: 0 6 6; OCCURRENCE CODE: 0 3; REPORT TYPE: L; REVISION NO.: 0
18 | ACTION TAKEN: X; FUTURE ACTION: F 19; EFFECT ON PLANT: Z 20; SHUTDOWN METHOD: Z 21; HOURS: 0 0 0 0; ATTACHMENT SUBMITTED: N 22; NPRO-4 FORM SUB.: Y 24; PRIME COMP. SUPPLIER: N 25; COMPONENT MANUFACTURER: B 0 8 0 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 | Caused by Instrument drift. In each case the instrument was calibrated and returned
1 1 | to service. Surveillance frequency was increased to once each week. New switches
1 2 | of different design are expected to arrive by October 1980 and will be installed as
1 3 | permanent corrective action.
1 4 |

1 5 | FACILITY STATUS: G 28; % POWER: 0 0 0 29; OTHER STATUS: NA 30; METHOD OF DISCOVERY: B 31; DISCOVERY DESCRIPTION: Surveillance 32
1 5 | ACTIVITY CONTENT RELEASED OF RELEASE: 7 33; AMOUNT OF ACTIVITY: NA 35; LOCATION OF RELEASE: NA 36
1 7 | PERSONNEL EXPOSURES NUMBER: 0 0 0 37; TYPE: Z 38; DESCRIPTION: NA 39
1 8 | PERSONNEL INJURIES NUMBER: 0 0 0 40; DESCRIPTION: NA 41
1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE: Z 42; DESCRIPTION: NA 43
2 0 | PUBLICITY ISSUED DESCRIPTION: N 44; NA 45

POOR ORIGINAL

8009030423 NAME OF PREPARER: W. Verne Childs PHONE: 315-342-3840