



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

TJC

JUL 23 1980

Docket No. 50-87

Westinghouse Electric Corporation
ATTN: Mr. G. W. Scholand, Manager
Westinghouse Nuclear
Training Center
505 Shiloh Boulevard
Zion, IL 60099

Gentlemen:

This refers to the routine inspection conducted by Mr. L. J. Hueter of this office on June 27, 1980, of activities at Westinghouse Nuclear Training Reactor authorized by NRC License No. R-119 and to the discussion of our findings with Mr. Roth and another member of your staff at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

No items of noncompliance with NRC requirements were identified during the course of this inspection.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room, except as follows. If this report contains information that you or your contractors believe to be proprietary, you must apply in writing to this office, within twenty days of your receipt of this letter, to withhold such information from public disclosure. The application must include a full statement of the reasons for which the information is considered proprietary, and should be prepared so that proprietary information identified in the application is contained in an enclosure to the application.

8009100085

Q

Westinghouse Electric
Corporation

- 2 -

JUL 23 1980

We will gladly discuss any questions you have concerning this inspection.

Sincerely,



A. B. Davis, Chief
Fuel Facility and
Material Safety Branch

Enclosure: IE Inspection
Report No. 50-87/80-05

cc w/encl:

Mr. J. Roth, Manager
Fundamentals and Training
Reactor
Mr. A. T. Sabo, Director, Licensing,
Safeguards & Safety
R. P. DiPiazza - 265, License
Administrator
Central Files
Reproduction Unit NRC 20b
PDR
NSIC
TIC