



Petrochemicals Company | P. O. Box 2509, Shirley Basin, Wyoming 82615 • Telephone: (307) 234-9341

A Unit of Getty Oil Company

August 8, 1980

U.S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive
Arlington, TX 76012

Gentlemen:

The following information is being provided as requested in your letter of July 28, 1980:

In reference to item 2.a of the Notice of Violation, the following plan has been put into action. When dust concentrations in excess of the protection factor for the half-mask respirators were recorded, visible dust was present in the air. Personnel have been instructed and areas posted accordingly that if visible dust is present in the air, half-mask respirators will not provide sufficient protection and will not be worn. In cases where it is necessary to enter areas where dust is visible in the air, a high efficiency Airstream respirator (protection factor 1000) must be worn. A copy of the Notice to Employees, which is posted at these areas, is enclosed.

In reference to Item 4, nine copies of the page changes to the Supplemental Radiation Safety Program concerning sampling locations were sent to Mr. Scaramo, Uranium Recovery Licensing Branch on July 22 for distribution. In the event that you have not received your copy I am enclosing another copy for your files.

In reference to Item 5, license condition 16 was amended in Amendment No.7 dated July 14, 1980. Copies of the amendment have been enclosed for your convenience.

Sincerely,

S.J. Pfaff
Radiation Coordinator

SJP:vg

Enclosures

8009100 222