



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555

September 5, 1980

TERA

Docket No. 50-293

Mr. A. Victor Morisi, Manager
Nuclear Operations Support
Department
Boston Edison Company
M/C NUCLEAR
800 Boylston Street
Boston, Massachusetts 02199

Dear Mr. Morisi:

We have reviewed your response dated January 4, 1980 to our November 9, 1979 letter concerning those portions of your ECCS evaluation models, dealing with fuel cladding swelling and incidence of rupture.

We find that you have adequately confirmed the representations made in your behalf by your fuel supplier. We, therefore, conclude that your response is acceptable and that no further action is necessary.

Sincerely,

Thomas A. Ippolito
Thomas A. Ippolito, Chief
Operating Reactors Branch #2
Division of Licensing

cc: See next page

8009180541

P

Mr. A. Victor Morisi
Boston Edison Company

- 2 -

September 5, 1980

cc:

Mr. Paul J. McGuire
Pilgrim Station Acting Manager
Boston Edison Company
RFD #1, Rocky Hill Road
Plymouth, Massachusetts 02360

Henry Herrmann, Esquire
Massachusetts Wildlife Federation
151 Tremont Street
Boston, Massachusetts 02111

Plymouth Public Library
North Street
Plymouth, Massachusetts 02360

Resident Inspector
c/o U. S. NRC
P. O. Box 867
Plymouth, Massachusetts 02360