

AUG 22 1988

License: 42-26928-01
Docket: 30-30429/88-01

Pro-Technics International, Inc.
ATTN: John W. Chisholm, President
14760 Memorial Drive
Suite 206
Houston, Texas 77079

Gentlemen:

This refers to the routine, unannounced radiation safety inspection conducted by Mr. L. Ricketson of this office on July 15, 1988, at your field station in Yukon, Oklahoma, of the activities authorized by NRC License 42-26928-01. Members of your staff were not available for the inspection or the discussion of our findings at the conclusion of the inspection; however, you were notified by telephone on July 26, 1988, of the inspection findings by Dr. Dale Powers.

The inspection was an examination of the activities conducted under the license as they relate to radiation safety and to compliance with the Commission's rules and regulations, and the conditions of the license. The inspection consisted of interviews of personnel sharing the address, independent measurements, and observations by the NRC inspector.

During this inspection, certain of your activities were found not to be conducted in full compliance with NRC requirements. Consequently, you are required to respond to this matter, in writing, in accordance with provisions of Section 2.201 of the NRC "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Your response should be based on the specifics contained in the Notice of Violation enclosed with this letter.

The response directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

Should you have any questions concerning this letter, we will be pleased to discuss them with you.

Sincerely,

Original Signed By

William L. Fisher, Chief
Nuclear Materials Safety Branch

Enclosure: (see next page)

RIV:NMIS *RP*
LTRicketson,dp
8/19/88

C:NMIS *DP*
DAPowers
8/16/88

C:NMSB *WLF*
WLFisher
8/22/88

8808300154
REG-4 LIC-30
42-26928-01

880822
FDC

2PP XA

A/1
[Handwritten signature]

Enclosure:
Appendix - Notice of Violation

cc:
Oklahoma Radiation Control Program Director

bcc:
DMB - Original (IE-07)
RDMartin
RLBangart
REHall
WLFisher
*DAPowers
LShea, RM/ALF (AR-2015)
*NMEPB
*MIS System
*RIV Files (2)
*RSTS Operator

*w/766