

## PUBLIC SERVICE INDIANA

October 30, 1989

Gibson Generating Station P.O. Box 408 Owensville, IN 47665

D. J. Sreniawski, Chief Nuclear Materials Safety Section 1 United States Nuclear Regulatory Commission Region III 799 Roosevelt Road Glen Ellyn, IL 60137

Dear Mr. Sreniawski:

In answer to your letter of October 23 and as discussed with Mr. Lambert the date of his phone survey, the AM-241 source is in a Texas Nuclear Alloy Identifier. This instrument has been stored in a controlled area and is used only by qualified personnel. It has been receiving all required wipe tests. The only problem was that it was not on the master inventory sheet I maintain and was not physically inventoried every six-months by my group. This instrument is now added to the master list and will be inventoried.

As discussed over the phone, this should correct the regulatory concern and I am considering this action to be the appropriate response to the October 23 letter.

Sincerely,

Ronald L. Richard

Superintendent, Chemical Operations &

Radiation Safety Officer

Ronald 2. Nichard

CSS

8912060253 891030 REG3 SUBJ PDC

NOV 3 1989 107