

040WMD6484DE

WM-64




Department of Energy  
Albuquerque Operations Office  
P.O. Box 5400  
Albuquerque, New Mexico 87115

RETURN ORIGINAL TO PDR, HQ.

MAR 28 1989

Mr. Edward F. Hawkins  
Licensing Branch 1  
Uranium Recovery Field Office  
Nuclear Regulatory Commission, Region IV  
P.O. Box 25325  
Denver, CO 80225



Dear Ed,

Enclosed for your review and concurrence are three (3) copies of the Final Remedial Action Plan (RAP) for the Lakeview, Oregon, uranium mill tailings site. Please note that several changes have been made since the Preliminary RAP was issued in April 1986. These have been highlighted in bold text for your reference.

Additionally, the Compliance Strategy for the Proposed Environmental Protection Agency groundwater standards has been included as Appendix F to the RAP. All changes to the original text have also been noted, for reference purposes, within the executive summary. In accordance with the Department of Energy/Nuclear Regulatory Commission Memorandum of Understanding, DOE requests your comments or concurrence within 45 days of receipt. Please advise the UMTRA Project Office of any additional information you may need to support your review of the RAP.

Should you have any questions, please contact Jolene Garcia of my staff at (505) 846-1238.

Sincerely,

Mark L. Matthews  
Acting Project Manager  
Uranium Mill Tailings Project Office

Enclosures (3)

cc w/enclosure:  
B. Taber, TAC (1)  
J. Garcia, UMTRA (1)  
Document Control (1)

DESIGNATED ORIGINAL

Certified By *Mary C. Hood*

8912130270 B90328  
PDR WASTE PNU  
WM-64

89-0535