DEC 0 5 1989

Docket Nos. 50-321, 50-366 License Nos. DPR-57, NPF-5

Georgia Power Company
ATTN: Mr. W. G. Hairston, III
Senior Vice President Nuclear Operations
P. O. Box 1295
Birmingham, AL 35201

Gentlemen:

SUBJECT: SYSTEMATIC ASSESSMENT OF LICENSEE PERFORMANCE (NRC INSPECTION REPORT NOS. 50-321/89-22 AND 50-366/89-22)

The Nuclear Regulatory Commission (NRC) Systematic Assessment of Licensee Performance (SALP) Board has completed its periodic evaluation of your Hatch facility for the period July 1, 1988, through September 30, 1989. The results of this evaluation are documented in the enclosed SALP Report. This report will be discussed with you at a public meeting to be held at your Hatch facility in Baxley, Georgia, on December 13, 1989, at 11:00 a.m.

The performance of your Hatch facility was evaluated in the functional areas of plant operations, radiological controls, maintenance/surveillance, emergency preparedness, security and safeguards, engineering/technical support, and safety assessment/quality verification. Although the functional areas evaluated during this assessment period are not identical to those evaluated in the previous period, a close correlation can be made for identifying changes in performance.

This assessment clearly indicates overall performance has substantially improved. During this SALP period, the Hatch facility has shown an improving trend in the areas of security and safeguards and engineering/technical support; and has substantially improved the level of performance in the areas of plant operations, maintenance/surveillance, emergency preparedness, and safety assessment/quality verification. The level of performance in the area of radiological controls remained the same as the previous SALP period. Management attention and involvement have been evident throughout the assessment period.

Your staff should be commended for their superior performance in a majority of the SALP functional areas. It will be a continuing challenge to maintain and improve upon this level of performance. With regard to improvements, the NRC staff has specifically recommended that you provide increased attention in the area of control of special processes with particular emphasis on technical oversight of contractor performance in the welding and NDE areas.

Any comments you have concerning our evaluation of the performance of your facility should be submitted to this office within 30 days following the date of our meeting. These comments will be considered in the development of the Final SALP Report. Your comments, a summary of our meeting, and my disposition of your comments will be issued as appendices to the Final SALP Report.

Should you have any questions concerning this letter, we will be glad to discuss them with you.

Sincerely.

James L. Milhoan for

Stewart D. Ebneter Regional Administrator

Enclosure: Initial SALP Report - Hatch

cc w/encl: R. P. McDonald, Executive Vice President, Nuclear Operations Georgia Power Company P. O. Box 1295 Birmingham, AL 35201

J. T. Beckham Vice President, Plant Hatch Georgia Power Company P. O. Box 1295 Birmingham, AL 35201

H. C. Nix General Manager, Plant Hatch Route 1, Box 429 Baxley, GA 31513

S. J. Bethay Manager Licensing - Hatch Georgia Power Company P. O. Box 1295 Birmingham, AL 35201

Shaw. Pittman, Potts and Trowbridge 2300 N Street, NW Washington, D. C. 20037

(cc w/encl cont'd - see page 3)

cc w/encl: (Cont'd) Charles H. Badger Office of Planning and Budget Room 610 270 Washington Street, SW Atlanta, GA 30334

J. Leonard Ledbetter. Director Environmental Protection Division Department of Natural Resources 205 Butler Street, SE. Suite 1252 Atlanta, GA 30334

Chairman Appling County Commissioners County Courthouse Baxley, GA 31513

State of Georgia

bcc w/encl: K. M. Carr, Chairman T. M. Roberts, Commissioner F. J. Remick. Commissioner K. C. Rogers, Commissioner J. R. Curtiss, Commissioner J. M. Taylor, EDO H. L. Thompson, Jr., EDO R. W. Borchardt, Regional Coordinator, EDO D. B. Matthews, NRR T. E. Murley, NRR S. Varga, NRR L. P. Crocker, NRR R. Nease, SALP Coordinator, NRR Regional Administrators, RI, RIII RIV. and RV K. Clark, RII, PAO A. Herdt. DRP. RII K. Brockman, DRP, RII L. Trocine, DRP, RII K. Landis, Chief, TSS NRC Resident Inspector DRS and DRSS Branch Chiefs, and Section Chiefs INPO IMPELL Document Control Desk

RII:DRP RII: DRP RII:NRR RII: DRP RII: DRS RII:DRP RII:NRR RII:DRP MARK

Florocker DMatthews CHehl therschoff JMenning KBrockman AHerdt LTrocine RII: DRSS RII: DRA JStohr JMilhoan 12/5/89 12/5/89 12/5 /89 12/5/89 12/5/89/12/5/89

Telecon

12/5/89 12/5/89



## UNITED STATES NUCLEAR REGULATORY COMMISSION REGION II 101 MARIETTA STREET, N.W. ATLANTA, GEORGIA 30323

DEC 0 1 1903

Docket Nos. 50-321, 50-366 License Nos. DPR-57, NPF-5

Georgia Power Company
ATTN: Mr. W. G. Hairston, III
Senior Vice President Nuclear Operations
P. O. Box 1295
Birmingham, AL 35201

Gentlemen:

SUBJECT: SYSTEMATIC ASSESSMENT OF LICENSEE PERFORMANCE

(NRC INSPECTION REPORT NOS. 50-321/89-22 AND 50-366/89-22)

The Nuclear Regulatory Commission (NRC) Systematic Assessment of Licensee Performance (SALP) Board has completed its periodic evaluation of your Hatch facility for the period July 1. 1988, through September 30, 1989. The results of this evaluation are documented in the enclosed SALP Report. This report will be discussed with you at a public meeting to be held at your Hatch facility in Baxley, Georgia, on December 13, 1989, at 11:00 a.m.

The performance of your Hatch facility was evaluated in the functional areas of plant operations, radiological controls, maintenance/surveillance, emergency preparedness, security and safeguards, engineering/technical support, and safety assessment/quality verification. Although the functional areas evaluated during this assessment period are not identical to those evaluated in the previous period, a close correlation can be made for identifying changes in performance.

This assessment clearly indicates overall performance has substantially improved. During this SALP period, the Hatch facility has shown an improving trend in the areas of security and safeguards and engineering/technical support; and has substantially improved the level of performance in the areas of plant operations, maintenance/surveillance, emergency preparedness, and safety assessment/quality verification. The level of performance in the area of radiological controls remained the same as the previous SALP period. Management attention and involvement have been evident throughout the assessment period.

Your staff should be commended for their superior performance in a majority of the SALP functional areas. It will be a continuing challenge to maintain and improve upon this level of performance. With regard to improvements, the NRC staff has specifically recommended that you provide increased attention in the area of control of special processes with particular emphasis on technical oversight of contractor performance in the welding and NDE areas.

Any comments you have concerning our evaluation of the performance of your facility should be submitted to this office within 30 days following the date of our meeting. These comments will be considered in the development of the Final SALP Report. Your comments, a summary of our meeting, and my disposition of your comments will be issued as appendices to the Final SALP Report.

Should you have any questions concerning this letter, we will be glad to discuss them with you.

Sincerely.

Stewart D. Ebneter Regional Administrator

Enclosure: Initial SALP Report - Hatch

cc w/encl:
R. P. McDonald. Executive Vice
President. Nuclear Operations
Georgia Power Company
P. O. Box 1295
Birmingham. AL 35201

J. T. Beckham Vice President, Plant Hatch Georgia Power Company P. O. Box 1295 Birmingham, AL 35201

H. C. Nix General Manager, Plant Hatch Route 1. Box 439 Baxley, GA 31513

S. J. Bethay Manager Licensing - Hatch Georgia Power Company P. O. Box 1295 Birmingham, AL 35201

Shaw, Pittman, Potts and Trowbridge 2300 N Street, NW Washington, D. C. 20037

(cc w/encl cont'd - see page 3)

..

cc w/encl: (Cont'd) Charles H. Badger Office of Planning and Budget Room 610 270 Washington Street, SW Atlanta, GA 30334

J. Leonard Ledbetter. Director Environmental Protection Division Department of Natural Resources 205 Butler Street. SE. Suite 1252 Atlanta. GA 30334

Chairman Appling County Commissioners County Courthouse Baxley, GA 31513

State of Georgia