



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION I
631 PARK AVENUE
KING OF PRUSSIA, PENNSYLVANIA 19406

730
25 AUG 1980

Docket No. 70-33

Texas Instruments Incorporated
ATTN: Mr. William K. Goetz
Manufacturing Manager,
Metal Systems Department
34 Forest Street
Attleboro, Massachusetts 02703

Gentlemen:

Subject: Inspection No. 70-33/80-08

This refers to the routine inspection conducted by Miss Lisa M. McKeown of this office on July 28-31, 1980, at the HFIR Facility, Attleboro, Massachusetts of activities authorized by NRC License No. SNM-23 and to the discussions of our findings held by Miss Lisa M. McKeown with Mr. William K. Goetz at the conclusion of the inspection.

Areas examined during this inspection are described in the Office of Inspection and Enforcement Inspection Report which is enclosed with this letter. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector.

Within the scope of this inspection, no items of noncompliance were observed.

In accordance with Section 2.790(d) of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, documentation of your control and accounting procedures for safeguarding special nuclear materials and your facility security procedures are exempt from disclosure; therefore, the enclosed inspection report will not be placed in the Public Document Room and will receive limited distribution.

No reply to this letter is required; however, should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

Walter G. Martin, Chief
Safeguards Branch

Enclosure:
Office of Inspection and Enforcement
Inspection Report No. 70-33/80-08
(Contains 2.790(d) Information)

8010230 120 C

25 AUG 1980

cc (w copy of report cover sheet only):
W. George, Assistant Vice President and Manager,
Metallurgical Materials Division
F. L. Sherman, Manager, HFIR Project