PACIFIC GAS AND ELECTRIC COMPANY

IP Chesis

77 BEILE STREET, BIST FLOOR . SAN FRANCISCO, CALIFORNIA 94106 . (415) 791-4211

MALCOLM H. FURBUSH

September 4, 1980

CLEAN WAST ON DECEMBER OF THE PROPERTY OF T

E. MARTH. MICHARDA DATA DAMAGE ALLEGATOR DATA TRANSPORTATION HITCHARD ALLEGATOR JULE DATA DATA JULIUS DA ANGERSTADA BERNATURA ALLEGATOR DATA ALLEGATOR

ROBERT OHLBACH

CHARLES T. VAN DEUSEN
PHILIP A CRANE, JR
HENRY J. LAPLANTE
JOHN B. GIBSON
ARTHUR L. HILLMAN JR
CHARLES W. TH. TRLL
DANIEL E. GIBSON
ASSITANT SEASON COUNTEL

CALLEY KANDERDON

DIANA TOURSHAM, NED

DIANA TOURSHAM, NED

DIANA TOURSHAM

DIANA TOURSHAM

DIANA TOURSHAM

DIANA TOURSHAM

DIANA TOURSHAM

DIANA TOURSHAM

PARTIN COURSE

A DEP DATASE
A DESCRIPTION
CONTROL OF STREET OF STREET
A STREET OF STREET
A STREET
A

Mr. R. H. Engelken, Director Office of Inspection and Enforcement Region V

U. S. Nuk lear Regulatory Commission 1990 North California Boulevard Walnut Creek Plaza, Suite 202 Walnut Creek, California 94596

> Re: Docket No. 50-133 License No. DPR-7

Dear Mr. Engelken:

This is in response to your letters dated July 31, 1 30 and August 15, 1980 which transmitted I.E. Bulletins Nos. 80-19 and 80-19 Revision I concerning use of mercury-wetted relays in the reactor protection system. A review has been performed and there are none of the above-mentioned relays in the reactor protection system at Humboldt Bay Power Plant.

It is estimated that approximately 3 hours have been expended to revie and respond to the subject bulletin.

Vary truly yours,

10.1.

CC: Director

Office of Inspection and Inforcement Division of Reactor Operations Inspection U. S. Nuclear Regulatory Commission Washington, D. C. 20555

Director
Document Management Branch
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

80.56