

LICENSEE EVENT REPORT
CONFROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 M A P P S 1 2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
CON'T    REPORT   L   6   0   5   0   -   0   2   9   3   7   0   9   0   1   8   0   9   1   6   8   0   9     SOURCE   SOURCE   60   61   DOCKET NUMBER   68   69   EVENT DATE   74   75   REPORT DATE   80   9     EVENT DESCRIPTION AND PROBABLE CONSEQUENCES   10   10   10   10   10   10   10   1
0 2 On September 1, 1980 Pilgrim Station Unit #1 changed its Station Organization as
indicated n Figures 6.2.1 and 6.2.2 of the Technical Specifications. The new
0 4 organization charts are attached to the LER.
0 5 1
0 6
07
0 8 1
SYSTEM CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCOD
17 REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 32
ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMEN' NPRD-4 PRIME COMP. COMPONENT MANUFACTURER  Z 18 G 19 Z 20 Z 21 0 0 0 0 0 Y 23 N 24 Z 25 Z 9 9 9 9 26
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  The changes to Boston Edison's Nuclear Organization result from Boston Edison's
continuing efforts to improve the management of Pilgrim Unit 1. Amendments to the
Tech. Specs. reflecting these organization changes will be submitted to the
Commission for their review and approval.
1 4 1
7 8 9 FACILITY STATUS STATUS  N.A.  OTHER STATUS  OTHER ST
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 N.A. LOCATION OF RELEASE 36 N.A. N.A.
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)  1 7 0 0 0 37 Z 38 N.A.
PERSONNEL INJURIES NUMBER 0 0 0 0 40 N.A.  N.A.
LOSS OF OR DAMAGE TO FACILITY 43  TYPE DESCRIPTION  N.A.
PUBLICITY NRC USE ONLY  ISSUED DESCRIPTION 45  N.A.
8 0092903 NAME OF PREPARER E.T. Graham PHONE: 617-746-7900





CODE: NSRAC - MEMBER OF NSRAC

ORC - MEMBER OF ORC
RO - NRC REACTOR OPERATOR LICENSE

SRO - NRC SENIOR REACTOR OPERATOR LICENSE