



MATERIAL TRANSMITTED HEREWITH
CONTAINS 2.790 INFORMATION
UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION II
101 MARIETTA ST., N.W., SUITE 3100
ATLANTA, GEORGIA 30303

Report No. 50-302/80-23

Docket No. 50-302

License No. DPR-72

Licensee: Florida Power Corporation
3201 34th Street, South
St. Petersburg, Florida 33733

Facility Name: Crystal River

Inspection near Crystal River, Florida

Inspectors: *R.D. Martin for*
T. F. Stetka, Senior Resident Inspector

6/27/80
Date Signed

R.D. Martin for
B. W. Smith, Resident Inspector (Trainee)

6/27/80
Date Signed

Approved by: *R.D. Martin*
R. D. Martin, Section Chief, RONS Branch

6/27/80
Date Signed

SUMMARY

Inspection on May 5-30, 1980 (Report No. 50-302/80-23)

Areas Inspected

Routine inspection by the resident inspector of plant operations, security, and radiological controls, Licensee Event Reports (LER's), licensee action on IE Information Notices, nonroutine events, surveillances tests, and tour of plant areas. The inspectors also observed the licensee's Emergency Plan drill conducted on May 29, observed plant operations on the back shift, and attended a meeting with NRR personnel on May 19. The inspection involved 129.5 hours onsite by two resident inspectors.

Results

Two items of noncompliance were identified (Infraction-Failure of security guards to either search personnel or require personnel to re-enter the weapons detector after the device had alarmed; Infraction-Failure of personnel to self-frisk prior to exiting the RCA).

S-F2 *XO* - *87*
Copy _____ of _____ Copies
11 Pages
This Document is not to be reproduced without specific approval of IE:II

8010010052