



ATOMIC POWER COMPANY •  
ENGINEERING OFFICE

TURNPIKE ROAD (RT. 9)  
WESTBORO, MASSACHUSETTS 01581  
617-366-9011

B.4.1.1  
WY 80-110

July 14, 1980

United States Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region I  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

Attention: Walter G. Martin, Chief  
Safeguards Branch

References: (a) License No. DPR-36 (Docket No. 50-309)  
(b) I&E Letter to MYAPC dated June 23, 1980 with  
enclosure IE Inspection Report No. 50-309/80-08

Dear Sir:

Subject: Response to Inspection Report No. 50-309/80-08


This letter is written in response to Reference (b) which indicated that certain security related activities were not conducted in full compliance with Nuclear Regulatory requirements, and the approved Maine Yankee Security Plan. The alleged items of noncompliance were noted during an inspection conducted on May 19-22, 1980 at Maine Yankee.

The enclosed information is submitted in answer to the alleged items of non-compliance and is considered proprietary in accordance with Title 10, Code of Federal Regulations, Part 2.790. Public disclosure of this material should be withheld.

We trust this information will be satisfactory to you; however, should you desire additional information please contact us at your convenience.

Very truly yours,

MAINE YANKEE ATOMIC POWER COMPANY

  
D. E. Moody  
Manager of Operations

RHG/smw  
Enclosure (Proprietary)

8010010 251