

Energy Systems Group  
8900 De Soto Avenue  
Canoga Park, CA 91304  
Telephone: (213) 341-1000  
TWX: 910-494-1237  
Telex: 181017



Rockwell  
International

PDR

71-5088

September 8, 1980

In reply refer to 80ESG-8499

Mr. Charles E. MacDonald, Chief  
Transportation Certification Branch  
Division of Fuel Cycle and Material  
Safety  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555



RECEIVED  
SEP 19 11 12

Dear Mr. MacDonald:

Subject: USA/5088/AF Certificate of Compliance Renewal for  
Models D34710-1 and J34710-2 Shipping Containers

In accordance with telephone conversations with Mr. R. H. Odegaard, enclosed are eight copies of our application for recertification of the shipping container identified by Certificate of Compliance USA/5088/AF. We have followed the format of Regulatory Guide 7.9 as far as practical. A verbatim retyped National Lead Test Report plus new drawings was furnished by University of Missouri Research Reactor (MURR) personnel to enable us to submit a complete data package.

As required in Section 170.31(11D) of 10 CFR 170, this application is for a renewal and thus is subject to a fee of \$150. Therefore, we are enclosing our check for \$150 in payment of the required fee.

Very truly yours,

M. E. Remley, Director  
Health, Safety & Radiation  
Services

ffh:1/2

Enclosures

cc: J. B. Just, EG&G  
K. C. Gerard, EG&G  
D. McGinty, MURR

Applicant	.....
Check No.	07118928
Amount/Fee Category	150-11D
Type of Fee	Ren
Date Check Rec'd	9/19/80
Received By	Gulim
	2 of 82-1

17354

THIS DOCUMENT CONTAINS  
POOR QUALITY PAGES

8010020074

C