



MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

JAMES P. McGAUGHY, JR.  
ASSISTANT VICE PRESIDENT

August 29, 1980

Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, N.W.  
Suite 3100  
Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Director

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station  
Units 1 and 2  
Docket Nos. 50-416/417  
File 0260/15525/15526  
PRD-80/45, Fractured Actuator to  
Damper Couplings  
AECM-80/198

On July 30, 1980, Mississippi Power & Light Company notified Mr. C. R. McFarland of your office of a Potentially Reportable Deficiency (PRD) concerning a fractured actuator to damper shaft couplings in the Diesel Generator Building Bay "A".

We are continuing to investigate this deficiency. After we have received data from the vendor, Pacific Air Products Company, we will complete our investigation and make a final determination on reportability under 10CFR50.55(e) and 10CFR21.

We expect to provide you our final evaluation of this deficiency by December 19, 1980. This item is also being tracked by Bechtel QAR F-206 and NCR 4930.

Yours truly,

701 J. P. McGaughy, Jr.  
Assistant Vice President,  
Nuclear Production

WDH:mc

cc: Mr. N. L. Scamplery  
Mr. R. B. McGehee  
Mr. T. B. Conner

Mr. Victor Stello, Director  
Division of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20535

8009080 376