

UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

IG 42
DK Central
files

AUG 11 1975

Commonwealth Edison Company
ATTN: Byron Lee, Jr.
Vice President
P. O. Box 767
Chicago, Illinois 60690

✓ Docket No. 50-10
Docket No. 50-237
Docket No. 50-249

Gentlemen:

This refers to the inspection conducted by Messrs. Johnson, Kister, and Erb on June 10-12, 17-18, 20, 23-27, and July 1-2, 1975, of activities at Dresden Nuclear Power Station Units 1, 2 and 3 authorized by NRC Operating Licenses No. DPR-2, No. DPR-19 and No. DPR-25 and to the discussions of our findings with Mr. Stephenson and others of your staff at the conclusion of the inspection.

A copy of our report of this inspection is enclosed and identifies the areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, interviews with plant personnel, and observations by the inspectors.

During this inspection, it was found that certain of your activities appear to be in noncompliance with NRC requirements. The items and reference to the pertinent requirements are listed under Enforcement Action in the Summary of Findings Section of the enclosed inspection report.

This notice is sent to you pursuant to the provisions of Section 2.201 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Section 2.201 requires you to submit to this office within twenty days of your receipt of this notice, a written statement or explanation in reply, including: (1) corrective steps which have been taken by you, and the results achieved; (2) corrective steps which will be taken to avoid further items of noncompliance; and (3) the date when full compliance will be achieved. Such a statement or explanation should be provided for each of the items listed.

An infraction identified through your management control program which was reported in a timely manner and corrected is set out in the Summary of Findings section of the attached inspection report. No additional information is needed for this item at this time.



8009150 629

9 POOR ORIGINAL

4

AUG 11 1975

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this notice, the enclosed inspection report, and your response to this notice will be placed in the NRC's Public Document Room. If this report contains any information that you or your contractors believe to be proprietary, it is necessary that you make a written application to this office, within twenty days of your receipt of this notice, to withhold such information from public disclosure. Any such application must include a full statement of the reasons for which it is claimed that the information is proprietary, and should be prepared so the proprietary information identified in the application is contained in a separate part of the document. Unless we receive an application to withhold information or are otherwise contacted within the specified time period, the written material identified in this paragraph will be placed in the Public Document Room.

Should you have any questions concerning this inspection, we will be glad to discuss them with you.

Sincerely yours,

Gaston Fiorelli, Chief
Reactor Operations Branch

Enclosure:

IE Inspection Reports
No. 050-010/75-13,
No. 050-237/75-19
and No. 050-249/75-15

cc w/encl:

B. Stephenson
Station Superintendent

bcc w/encl:

PDR
Local PDR
NSIC
TIC
Anthony Roisman, Esq