

September 15, 1980

Mr. James G. Keppler
Regional Director
Directorate of Regulatory Operations
Region III
U. S. Nuclear Regulatory Commission
Glen Ellyn, IL 60137

Reference: Zion Generating Station Docket No. 50-304/DPR-48

Technical Specification, Section 6.6.2

Dear Mr. Keppler:

Enclosed please find Reportable Occurrence Report No. 50-304/80-03 for Zion Generating Station. This occurrence was originally reported to Region III, Directorate of Regulatory Operations by telephone on 8/16/80 and by telegram/mailgram on 8/18/80. It was reclassified to a thirty day report 8/29/80.

This report is submitted to you in accordance with the requirements of the Technical Specifications, Section 6.6.2.b.2 which states that conditions leading to operation in a degraded mode permitted by a limiting condition for operation or plant shutdown required by a limiting condition for operation requires a thirty day written report.

Very truly yours,

K. L. Graesser Superintendent Zion Station

Enclosure: Reportable Occurrence Report No. 50-304/80-03

SEP 1 6 1980