

Appendix B

NOTICE OF VIOLATION

Northern States Power Company

Docket No. 50-282
Docket No. 50-306

Based on the Health Physics Appraisal conducted May 5-15, 1980, it appears that certain of your activities were in noncompliance with NRC requirements, as noted below. The item is an infraction.

Technical Specification 6.5.B.1 requires that individuals permitted to enter a high radiation area be provided with a radiation monitoring device which continuously indicates the radiation dose rate in the area.

Contrary to the above, several operations personnel stated that they did not routinely take a dose rate indicating device into high radiation areas when dressed in full anticontamination clothing.