

APPENDIX A

NOTICE OF VIOLATION

Island Creek Coal Company

License No. 45-15262-02

Based on the NRC inspection July 23, 1980, certain of your activities were apparently not conducted in full compliance with NRC requirements as indicated below. These items have been categorized as described in correspondence to you dated December 31, 1974.

- A. License Condition 16A.(1) requires that each sealed source shall be tested for leakage and/or contamination at intervals not to exceed six months.

Contrary to the above, the 8.6 millicurie Cesium-137 and 40 millicurie Americium-241 sealed sources possessed by you in a Troxler 3400 Series surface moisture-density gauge have not been leak tested since April, 1979.

- B. 10CFR19.11(c) requires that Form NRC-3 "Notice to Employees" shall be posted by each licensee wherever individuals work in or frequent any portion of a restricted area.

Contrary to the above, the Form NRC-3 was not posted in your facility at the time of this inspection on July 23, 1980.