
NIS-80-752



August 29, 1980

J. A. Hind, Chief Safeguards Branch U. S. Nuclear Regulatory Commission Region III 799 Roosevelt Road Glen Ellyn, Illinois 60137

> License No. SNM-33 Docket No. 70-36

Dear Mr. Hind:

The enclosed report is submitted as requested by your letter dated August 8, 1980, concerning IE Inspection report 70-036/80-03.

Please advise if any additional information is required.

Very truly yours,

COMBUSTION ENGINEERING, INC.

H. E. Eskridge

Supervisor, Nuclear Licensing,

Salety and Accountability

jb Enclosure

August 28, 1980 SNM-33

STATUS OF APPARENT NON-COMPLIANCE ITEM IDENTIFIED IN IE INSPECTION REPORT 70-036/80-03

Following is the current status of the subject item:

All individuals authorized to sign internal transfer forms have been reminded that both a shipper's and a receiver's signature is required for each transfer. Routine audits will be made to avoid further non-compliance. We are now in full compliance on this item.