
O. Lanham



REGULATORY DOSKET FILE COPY

November 22, 1977

BBS LTR #1086-77



James G. Keppler, Regional Director
Directorate of Regulatory Operations - Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Reportable Occurrence Report #77-042/03L-0, Docket #050-010 is hereby submitted to your office in accordance with Dresden Nuclear Power Station Technical Specifications 6.6.8.2.(a), Engineered Safety feature instrument settings found to be less conservative than those established by the Technical Specifications but which do not prevent the fulfillment of the functional requirements of affected systems.

B. Stephenson

Station Superintendent

Dresden Nuclear Power Station

BBS:dlz

Enclosure

cc: Director of Inspection & Enforcement

Director of Management Information & Program Control

File/NRC

MCV 3 0 1977